



Maintenance Aging Report - Oklahoma - OKC

Regional maintenance aging report for Oklahoma - OKC, listing all hotel items at 14+ days with critical maintenance items first.

09/05/2026 | Produced: 7:51 AM

HOTELS IN
REGION

3

From the contact
workbook

14+ DAY ITEMS

16

Current regional
aging bucket

CRITICAL ITEMS

5

Water, electric,
PTAC, HVAC items
first

OLDEST ITEM

75

Days old in this
region

Executive Summary

Oklahoma - OKC currently has **16** maintenance item(s) at **14+ days** across **3** hotel(s). Critical items are listed first inside each hotel. Leading critical categories in this region are **water (4)**, **ptac/hvac (1)**, **electric (1)**.

Regional Leadership

- **Regional Manager:** Terra Smith
- **Regional Maintenance:** Charles Lengele

What Needs Attention Now

- **OKC - Northwest** has 14 item(s) at 14+ days, oldest at 75 day(s), with 4 critical.
- **OKC - Airport** has 1 item(s) at 14+ days, oldest at 17 day(s), with 1 critical.
- **OKC - Frontier** has 1 item(s) at 14+ days, oldest at 15 day(s), with 0 critical.

14+ Day Items by Hotel

OKC - Frontier

OK - OOF · 1 item(s), oldest 15 day(s), 0 critical

- **STANDARD** **24924-1** · 15 day(s) old · created 08/21/2026
107 SHELF NEEDS TO BE REPLACED IN BATHROOM.
Priority: Normal · Category: general

OKC - Airport

OK - OOA · 1 item(s), oldest 17 day(s), 1 critical

- **CRITICAL** **24743-1** · 17 day(s) old · created 08/19/2026
2106 WATER DOES NOT TURN OFF COMPLETELY ON SHOWER.
Priority: Normal · Category: water

OKC - Northwest

OK - OON · 14 item(s), oldest 75 day(s), 4 critical

- **CRITICAL** **23842-1** · 35 day(s) old · created 08/01/2026
unit 162 ceiling damage from 262 ptac leak
Priority: Normal · Category: water, ptac/hvac
- **CRITICAL** **24460-1** · 23 day(s) old · created 08/13/2026
241 both kitchen outlets dont work
Priority: Normal · Category: electric
- **CRITICAL** **24916-1** · 15 day(s) old · created 08/21/2026
246 - Shower Surround
Priority: Normal · Category: water
- **CRITICAL** **24917-1** · 15 day(s) old · created 08/21/2026
222 - Shower Surround must be fixed
Priority: Normal · Category: water
- **STANDARD** **22233-1** · 75 day(s) old · created 06/22/2026
tile needs redone in multiple 2nd floor units (outside calls for tile work)
Priority: Normal · Category: general
- **STANDARD** **24262-1** · 25 day(s) old · created 08/11/2026
lights that are out along walkways:
Priority: Normal · Category: general
- **STANDARD** **24457-1** · 23 day(s) old · created 08/13/2026
225 bathroom sink filter
Priority: Normal · Category: general
- **STANDARD** **24463-1** · 23 day(s) old · created 08/13/2026
200 need bathroom fan installed
Priority: Normal · Category: general
- **STANDARD** **24470-1** · 23 day(s) old · created 08/13/2026
251 need bathroom fan
Priority: Normal · Category: general
- **STANDARD** **24471-1** · 23 day(s) old · created 08/13/2026
204 need bathroom fan in master bath

Priority: Normal · Category: general

- **STANDARD 24660-1** · 19 day(s) old · created 08/17/2026
238 need bathroom fan

Priority: Normal · Category: general

- **STANDARD 24865-1** · 16 day(s) old · created 08/20/2026
147 bathroom wall patch behind needs redone

Priority: Normal · Category: general

- **STANDARD 24913-1** · 15 day(s) old · created 08/21/2026
Covered roof in front of the office the light on top is falling out

Priority: Normal · Category: general

- **STANDARD 24948-1** · 14 day(s) old · created 08/22/2026
Floodlights to the right of the building is not working

Priority: Normal · Category: general

Recommended Actions

- Clear critical water, electric, PTAC, and HVAC items first before routine backlog work.
- Force same-day ownership on any hotel carrying multiple critical aged items.
- Use this region-specific view to push daily follow-up by hotel until all 14+ day items are closed.