



# Maintenance Aging Report - Arkansas - South

Regional maintenance aging report for Arkansas - South, listing all hotel items at 14+ days with critical maintenance items first.

05/15/2026 | Produced: 7:51 AM

HOTELS IN  
REGION

**7**

From the contact  
workbook

14+ DAY ITEMS

**10**

Current regional  
aging bucket

CRITICAL ITEMS

**1**

Water, electric,  
PTAC, HVAC items  
first

OLDEST ITEM

**32**

Days old in this  
region

## Executive Summary

**Arkansas - South** currently has **10** maintenance item(s) at **14+ days** across **5** hotel(s). Critical items are listed first inside each hotel. Leading critical categories in this region are **water (1)**.

## Regional Leadership

- **Regional Manager:** Shannon Conway
- **Regional Maintenance:** Benis Blanco

## What Needs Attention Now

- **Little Rock - Chenal** has 1 item(s) at 14+ days, oldest at 15 day(s), with 1 critical.
- **Little Rock - University** has 3 item(s) at 14+ days, oldest at 15 day(s), with 0 critical.
- **Benton - Thirty** has 2 item(s) at 14+ days, oldest at 32 day(s), with 0 critical.
- **Benton - South** has 2 item(s) at 14+ days, oldest at 21 day(s), with 0 critical.
- **Little Rock - Breckenridge** has 2 item(s) at 14+ days, oldest at 17 day(s), with 0 critical.

## 14+ Day Items by Hotel

---

### Benton - South

AR - BS · 2 item(s), oldest 21 day(s), 0 critical

- **STANDARD 20206-1** · 21 day(s) old · created 04/24/2026  
5 metal signs need put on posts and mounted in the ground (I have the signs LLC 2 Designated Dog Area signs need put up in the following Areas: 1 - small dog park area between rooms 136 & 137 1 by the big tree in the field beside room 160 2 No Poop & Pee Zones: 1 - Grassy area by Room 170 1 - Grassy area by sidewalk in front of gate between manager house and Room 141 1 SLOW Children at Play sign By Tree in gravel area in center of property between Laundromat, Manager Office, and Rooms 131 - 138  
Priority: Low · Category: general
  - **STANDARD 20207-1** · 21 day(s) old · created 04/24/2026  
Office & Manager Residence - Gutter needs cleaned out and down spout LLC  
Priority: Low · Category: general
- 

### Benton - Military

AR - BM · No items in this aging bucket.

None in this aging bucket.

---

### Benton - Thirty

AR - BT · 2 item(s), oldest 32 day(s), 0 critical

- **STANDARD 19794-1** · 32 day(s) old · created 04/13/2026  
Carport needs to be pressure washed to get the cob webs and dirty off, might better.  
Priority: Normal · Category: general
  - **STANDARD 20282-1** · 17 day(s) old · created 04/28/2026  
Gutters need to be repaired  
Priority: Normal · Category: general
- 

### Little Rock - Otter

AR - LRO · No items in this aging bucket.

None in this aging bucket.

---

### Little Rock - University

AR - LRU · 3 item(s), oldest 15 day(s), 0 critical

- **STANDARD 20421-1** · 15 day(s) old · created 04/30/2026  
Side gate by 1000 building ( right side if youre front side facing 1000 building ) missing boards, cant latch from both sides due to the updated attempts to fix)  
Priority: Normal · Category: general
- **STANDARD 20422-1** · 15 day(s) old · created 04/30/2026  
whole property needs to be pressure washed

Priority: Normal · Category: general

- **STANDARD** **20424-1** · 15 day(s) old · created 04/30/2026  
parking lot needs redone - entire parking lot needs relined - several pot holes throughout parking lot ( backside of 1000 building , front corner of 2000 building, backside of 3000 building, drive through lane leading to from frontside of 3000 building to backside 3000 building closet to roadway

Priority: Normal · Category: general

---

### Little Rock - Breckenridge

AR - LRB · 2 item(s), oldest 17 day(s), 0 critical

- **STANDARD** **20300-1** · 17 day(s) old · created 04/28/2026  
need sound barriers for fire alarms.
- **URGENT** **20388-1** · 15 day(s) old · created 04/30/2026  
Manager door needs new door knob.

Priority: Urgent · Category: general

---

### Little Rock - Chenal

AR - LRC · 1 item(s), oldest 15 day(s), 1 critical

- **CRITICAL** **20387-1** · 15 day(s) old · created 04/30/2026  
Room 133 Light in Bathroom does not work Hole behind the toilet needs patched up  
Toilet rocks back and forth

Priority: Normal · Category: water

## Recommended Actions

- Clear critical water, electric, PTAC, and HVAC items first before routine backlog work.
- Force same-day ownership on any hotel carrying multiple critical aged items.
- Use this region-specific view to push daily follow-up by hotel until all 14+ day items are closed.