



Maintenance Aging Report - Executive Level

Executive maintenance aging report across all regions, limited to 30+ day items with critical maintenance items first.

06/23/2026 | Produced: 7:50 AM

REGIONS WITH
30+ ITEMS

4

Regions carrying
executive
exceptions

30+ DAY ITEMS

8

Executive threshold
scope

CRITICAL ITEMS

4

Water, electric,
PTAC, HVAC items
first

OLDEST ITEM

62

Days old in
executive scope

Executive Summary

There are **8** maintenance item(s) at the **30+ day** executive threshold across **4** region(s). Critical maintenance items are surfaced first so leadership can isolate the highest operating risk before reviewing routine backlog.

What Needs Attention Now

- **Arkansas - South** has 1 item(s) at 30+ days, with 0 critical and oldest at 34 day(s).
- **Oklahoma - Tulsa** has 4 item(s) at 30+ days, with 2 critical and oldest at 36 day(s).
- **Oklahoma - OKC** has 1 item(s) at 30+ days, with 1 critical and oldest at 49 day(s).
- **Louisiana** has 2 item(s) at 30+ days, with 1 critical and oldest at 62 day(s).

Executive 30+ Day Items by Region

Arkansas - South

Little Rock - University

AR - LRU · 1 item(s), oldest 34 day(s), 0 critical

- **STANDARD 21067-1** · 34 day(s) old · created 05/20/2026
several of our bulbs are out on our big joe eagle sign on the front entrance of
Priority: Normal · Category: general
-

Oklahoma - Tulsa

Tulsa - Hilti

OK - OTH · 4 item(s), oldest 36 day(s), 2 critical

- **CRITICAL 20959-1** · 36 day(s) old · created 05/18/2026
need the drains outside in court yard covered the holes and the grates
Priority: Normal · Category: water
 - **CRITICAL 20990-1** · 36 day(s) old · created 05/18/2026
Guest Laundry Room: Leak behind the first washer closest to the commercial
Priority: Normal · Category: water
 - **STANDARD 20992-1** · 36 day(s) old · created 05/18/2026
Guest Laundry Room: behind the row of dryers the ventilation system is not hazard to the guests and employees due to slipping.
Priority: Normal · Category: general
 - **STANDARD 21009-1** · 35 day(s) old · created 05/19/2026
HOTEL HAS INFESTATION OF MICE
Priority: Normal · Category: general
-

Oklahoma - OKC

OKC - Northwest

OK - OON · 1 item(s), oldest 49 day(s), 1 critical

- **CRITICAL 20539-1** · 49 day(s) old · created 05/05/2026
!! power for laundry door need hooked up now that B LINE has been out here
Priority: Normal · Category: electric
-

Lousiana

Baton Rouge - Gwenadele

LA - BRG · 1 item(s), oldest 35 day(s), 1 critical

- **CRITICAL 21036-1** · 35 day(s) old · created 05/19/2026
331 fix ptac-missing parts
Priority: Normal · Category: ptac/hvac
-

Baton Rouge - Boardwalk

LA - BRB · 1 item(s), oldest 62 day(s), 0 critical

- **STANDARD** **20100-1** · 62 day(s) old · created 04/22/2026

back parking lot lights not working

Priority: Normal · Category: general

Recommended Actions

- Clear critical maintenance items first, regardless of region, before non-critical aging backlog.
- Escalate every 30+ day critical item into direct leadership review until closed.
- Use the regional packets to force accountability at the hotel level after leadership identifies exceptions.