



EAGLE SUITES®

Maintenance Aging Report

Leadership roll-up of open hotel-level maintenance work orders by aging threshold.

05/16/2026 | Produced: 7:51 AM

OPEN WORK
ORDERS

175

Current source
report scope

EXECUTIVE 30+
DAYS

5

Across 4 hotel(s)

REGIONAL 14+
DAYS

31

Across 13 hotel(s)

URGENT OPEN
ITEMS

19

Marked urgent in
source

Executive Summary

There are **5** open work order(s) at the executive 30+ day threshold and **31** open work order(s) at the regional 14+ day threshold. The current aged backlog is concentrated most heavily at **North Little Rock - Gray Road** with 5 item(s). This report is built to keep the executive view exception-based and the regional view operational.

What Needs Attention Now

- **Baton Rouge - Airline** has 2 item(s) at 30+ days old, oldest at 49 day(s), including urgent work.
- **Tulsa - E 52nd Street** has 1 item(s) at 30+ days old, oldest at 59 day(s).
- **Benton - I-30** has 1 item(s) at 30+ days old, oldest at 33 day(s).
- **North Little Rock - Gray Road** has 5 item(s) at 14+ days old, oldest at 26 day(s), 0 urgent.
- **Baton Rouge - Airline** has 4 item(s) at 14+ days old, oldest at 49 day(s), 1 urgent.
- **Conway - Skyline** has 3 item(s) at 14+ days old, oldest at 16 day(s), 1 urgent.

Executive Level, 30+ Day Items

Baton Rouge - Airline

2 item(s), oldest 49 day(s), 1 urgent

Regional Level, 14+ Day Items

North Little Rock - Gray Road

5 item(s), oldest 26 day(s), no urgent items

- **19093-1** · Normal · 49 day(s) old · created 03/28/2026
support pole on side of building 3 needs repaired. Airline
- **19829-1** · Urgent · 32 day(s) old · created 04/14/2026
FIX FENCE ACROSS FROM BUILDING 4 BY THE APT COMPLEX PLEASE Airline

Tulsa - E 52nd Street

1 item(s), oldest 59 day(s), no urgent items

- **18665-1** · Normal · 59 day(s) old · created 03/18/2026
CAMERA'S BY ROOM 145 AND THE FIRST FLOOR END LAUNDRY ROOM

Benton - I-30

1 item(s), oldest 33 day(s), no urgent items

- **19794-1** · Normal · 33 day(s) old · created 04/13/2026
Carport needs to be pressure washed to get the cob webs and dirty off, might better.

Baton Rouge - Boardwalk

1 item(s), oldest 32 day(s), no urgent items

- **19846-1** · Normal · 32 day(s) old · created 04/14/2026
A/C on 3rd floor for electrical room not kicking on and breaker is tripping

- **20023-1** · Normal · 26 day(s) old · created 04/20/2026
Room 419 front wall, window, and front door all need to be replaced after car
- **20025-1** · Normal · 26 day(s) old · created 04/20/2026
There is a large hole in the fence behind the dumpster across from Daniels
- **20146-1** · Normal · 23 day(s) old · created 04/23/2026
There is a hole in the fence behind the first building, where the fences meets
- **20407-1** · Normal · 16 day(s) old · created 04/30/2026
Property Sign in front of warehouse is damaged.
- **20449-1** · Normal · 15 day(s) old · created 05/01/2026
Room 543 needs breaker replaced (should have already been ordered by the

Baton Rouge - Airline

4 item(s), oldest 49 day(s), 1 urgent

- **19093-1** · Normal · 49 day(s) old · created 03/28/2026
support pole on side of building 3 needs repaired. Airline
- **19829-1** · Urgent · 32 day(s) old · created 04/14/2026
FIX FENCE ACROSS FROM BUILDING 4 BY THE APT COMPLEX PLEASE Airline
- **20312-1** · Normal · 18 day(s) old · created 04/28/2026
rm 116 vacant. Add shelves to upper cabinet. Airline
- **20361-1** · Normal · 17 day(s) old · created 04/29/2026
room 424 occupied clean bathroom threshold Airline

Conway - Skyline

3 item(s), oldest 16 day(s), 1 urgent

- **20383-1** · Normal · 16 day(s) old · created 04/30/2026
NEED QUEEN BED FRAME FOR 201, 204, 207, 227, 228, 231
 - **20428-1** · Urgent · 16 day(s) old · created 04/30/2026
NEEDS BLINDS 52 X 72 Skyline Maintenance
 - **20430-1** · Normal · 16 day(s) old · created 04/30/2026
NEED MISC FURNITURE PICKED UP BEHIND RESTURANT. Jeremy Lankford, Skyline Maintenance
-

Little Rock - University

3 item(s), oldest 16 day(s), no urgent items

- **20421-1** · Normal · 16 day(s) old · created 04/30/2026
Side gate by 1000 building (right side if youre front side facing 1000 building) missing boards, cant latch from both sides due to the updated attempts to fix)
 - **20422-1** · Normal · 16 day(s) old · created 04/30/2026
whole property needs to be pressure washed
 - **20424-1** · Normal · 16 day(s) old · created 04/30/2026
parking lot needs redone - entire parking lot needs relined - several pot holes throughout parking lot (backside of 1000 building , front corner of 2000 building, backside of 3000 building, drive through lane leading to from frontside of 3000 building to backside 3000 building closet to roadway
-

Tulsa - E 52nd Street

2 item(s), oldest 59 day(s), no urgent items

- **18665-1** · Normal · 59 day(s) old · created 03/18/2026
CAMERA'S BY ROOM 145 AND THE FIRST FLOOR END LAUNDRY ROOM
- **20455-1** · Normal · 15 day(s) old · created 05/01/2026
NEED THE BIG POWER WASHER

Benton - I-30

2 item(s), oldest 33 day(s), no urgent items

- **19794-1** · Normal · 33 day(s) old · created 04/13/2026
Carport needs to be pressure washed to get the cob webs and dirty off, might better.
- **20282-1** · Normal · 18 day(s) old · created 04/28/2026
Gutters need to be repaired

Baton Rouge - Boardwalk

2 item(s), oldest 32 day(s), no urgent items

- **19846-1** · Normal · 32 day(s) old · created 04/14/2026
A/C on 3rd floor for electrical room not kicking on and breaker is tripping
- **20100-1** · Normal · 24 day(s) old · created 04/22/2026
back parking lot lights not working

Rock - W Markham Street Little

2 item(s), oldest 23 day(s), 1 urgent

- **20140-1** · Urgent · 23 day(s) old · created 04/23/2026
The building needs to be pressure washed.
- **20173-1** · Normal · 23 day(s) old · created 04/23/2026
Building lights on the street side are out of order

Benton South

2 item(s), oldest 22 day(s), no urgent items

- **20206-1** · Low · 22 day(s) old · created 04/24/2026
5 metal signs need put on posts and mounted in the ground (I have the signs LLC 2 Designated Dog Area signs need put up in the following Areas: 1 - small dog park area between rooms 136 & 137 1 by the big tree in the field beside room 160 2 No Poop & Pee Zones: 1 - Grassy area by Room 170 1 - Grassy area by

sidewalk in front of gate between manager house and Room 141 1
SLOW Children at Play sign By Tree
in gravel area in center of property
between Laundromat, Manager
Office, and Rooms 131 - 138

- **20207-1** · Low · 22 day(s) old ·
created 04/24/2026
Office & Manager Residence -
Gutter needs cleaned out and down
spout LLC

Baton Rouge - Gwenadele

2 item(s), oldest 21 day(s), 1 urgent

- **20232-1** · Normal · 21 day(s) old ·
created 04/25/2026
223 needs headboard
- **20479-1** · Urgent · 14 day(s) old ·
created 05/02/2026
ROOM 328 HAS A HOLE IN THE
BATHROOM DOOR

Eagle Suites - Breckenridge

2 item(s), oldest 18 day(s), 1 urgent

- **20300-1** · Normal · 18 day(s) old ·
created 04/28/2026
need sound barriers for fire alarms.
- **20388-1** · Urgent · 16 day(s) old ·
created 04/30/2026
Manager door needs new door
knob.

Jacksonville - Shamrock

1 item(s), oldest 22 day(s), no urgent items

- **20186-1** · Normal · 22 day(s) old ·
created 04/24/2026
500 Building - Poor Lighting around
500 building

Little Rock - Hardin Road

1 item(s), oldest 16 day(s), no urgent items

- **20387-1** · Normal · 16 day(s) old ·
created 04/30/2026
Room 133 Light in Bathroom does
not work Hole behind the toilet

needs patched up Toilet rocks back and forth

Pattern Intelligence

- Total open work orders in source report: **175**, with **19** marked urgent.
- Executive threshold (30+ days): **5** item(s) across **4** hotel(s).
- Regional threshold (14+ days): **31** item(s) across **13** hotel(s).
- Most concentrated aging backlog is at **North Little Rock - Gray Road** with **5** item(s) currently at the 14+ day threshold.

Recommended Actions

- Escalate any **urgent** item that reaches 14 days old into same-day regional review instead of allowing it to roll deeper into backlog.
- Assign one owner per hotel for aged work orders and require a daily status comment until closure.
- Separate recurring PTAC / HVAC parts shortages from normal room-turn tasks so material constraints do not hide in general backlog.
- For the executive view, keep the 30+ day section intentionally short and exception-based. If that section is empty, leadership should read that as backlog still recoverable.

Source Notes

- Source file: **Eagle Suites Maintenance**
- Assigned user filter in source: **All**
- Status scope: **New, Assigned, Scheduled, and Waiting**
- Aging thresholds used here: **30+ days for executive** and **14+ days for regional**